



Rydis H68 Pro Bumper Replacement

Replace your Moneual RYDIS H68 Pro bumpers to get your vacuum to stop bumping into objects.

Written By: Joe Balduz



INTRODUCTION


Is your vacuum bumping into everything? Replacing the bumpers may solve the problem.



TOOLS:

- [Phillips #1 Screwdriver](#) (1)
 - [Metal Spudger](#) (1)
-

Step 1 — Battery



- Flip the vacuum over so that the wheels are facing you.
- Use a Phillips #1 screwdriver to remove the four 10mm screws that surround the battery cover.

Step 2



- Lift up the battery cover to reveal the battery.
- Remove the battery.

Step 3 — Bumper



- Remove the eight 10 mm Phillips #1 screws.

Step 4



- Hold the front bumper and pull it off.
- i** It requires a lot of force to pull the bumper off.

Step 5



- Pry off the back bumper by going around the entire top of the bumper with the metal spudger.

To reassemble your device, follow these instructions in reverse order.

This document was last generated on 2017-09-09 08:56:05 AM.